

7000 SERIES AFF AIR TOOL DISPLAY ASSEMBLY INSTRUCTIONS



7000 SERIES AFF AIR TOOL DISPLAY ASSEMBLY INSTRUCTIONS

Contents:

- Side panels (2)
- Upper molding (1)
- Lower molding (1)
- Main panel (1)
- Tool holders (12)
- Couplers (24)
- Screws (10 x 1", 6 x 1/2")
- Display cards

Step One:

- Attach upper and lower moldings to main panel using 1/2" screws in pre-drilled holes. The screws for upper molding go in the front of the molding and the screws for the lower molding go in the back of the molding.
- Insert coupler into the tool holder so that the male end is at the outside of the 90° bend on the tool holder.
- Thread a second fitting onto the first fitting and tighten.
- Repeat this step for all tool holders.

Step Two:

- Slide 4 tool holders into the 2 top slots.
- Slide 4 more tool holders into the next 2 slots.
- Slide the final 4 tool holders into the bottom 2 slots.

Step Three:

- To use the display as a shelf mount unit: place one side panel on the end of the main panel with the flange to the bottom of the display and attach it using screws in pre-drilled holes. Repeat this step with the other end panel.
- To use the display as a wall mount unit: place one side panel on the end of the main panel with the flange to the back of the display. **NOTE: The bulb shaped end of the keyholes in the flange must be to the bottom of the display.** Attach side panel to the main panel using screws in the pre-drilled holes.
- Repeat this step with the other end panel. The unit may now be attached to the wall by means of screws. Set into the wall at a distance apart which is equal to the distance between the keyholes on the display. **Note: Use one screw for each keyhole.**

Step Four:

- Mount each tool onto the display by threading the tool's air inlet onto the fitting.